529

NTRA	L INTELLIGENCE A	GENCY	
IEOD/	MATION REPORT	tional Defense of the ing of Title 18, Section amended. Its transmi	ins information affecting the Na- United States, within the mean- ons 793 and 794, of the U.S. Code, as ission or revelation of its contents insulthorized person is prohibited
		by law. The reprodu	nuction of this form is prohibited.
6, 1	be forther dook at small	RET/CONTROL US OFFICIALS ONLY SECURITY INFORMATION	
			50X1-HUN
4y	The montral was wash aga.	All bunks and Paris	
I IL ITOM	USSR (Arctic)	REPORT	
BJECT	Port of Arkhangel	SK DATE DISTR.	18 September 1953
	a.	7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7	is incomments
TE OF I	NEO.	REQUIREMENT :	NO. RD
	NUMBER OF THE PROPERTY OF THE	REFERENCES	50V1 LILIN
ACE ACC	QUIKED	क्किक के किस के किस 	50X1-HUM
		E EVALUATIONS IN THIS REPORT ARE DEFINITIVE.	
	THE	E APPRAISAL OF CONTENT IS TENTATIVE.  (FOR KEY SEE REVERSE)	50X1-HUN
1.	side of Solombala (N 64 four vessels for loadin	-36, 2 40-33). The quay is long end	there is room
1.	four vessels for loadin		ough to berth
2.	four vessels for loadin	-36, <b>E</b> 40-33). The quay is long end g purposes, while at the upper end waiting a loading berth.	ough to berth there is room 50X1-HUM
	four vessels for loadin for two other vessels a There is plenty of wate on the quay. The quay	-36, <b>E</b> 40-33). The quay is long end g purposes, while at the upper end waiting a loading berth.  or alongside this quay;  There is no cargo handling equipitself is a properly constructed who	ough to berth there is room  50X1-HUM  pment or warehouses arf; it is built
	four vessels for loadin for two other vessels a There is plenty of wate on the quay. The quay between piles, which we	-36, <b>E</b> 40-33). The quay is long end g purposes, while at the upper end waiting a loading berth.  There is no cargo handling equipitself is a properly constructed where driven into the river bed and the	ough to berth there is room  50X1-HUM  pment or warehouses arf; it is built e sloping river  50X1-HUN
	four vessels for loadin for two other vessels a There is plenty of wate on the quay. The quay between piles, which we bank, and it is faced w used as the waiting ber	The quay is long end g purposes, while at the upper end waiting a loading berth.  There is no cargo handling equipitself is a properly constructed where driven into the river bed and the rith stone. The upper part of the quay the, is approximately 500 feet long	ough to berth there is room  50X1-HUM  pment or warehouses arf; it is built e sloping river uay, which is , but it consists
	four vessels for loadin for two other vessels a There is plenty of wate on the quay. The quay between piles, which we bank, and it is faced w used as the waiting ber only of piles. The int	There is no cargo handling equipitself is a properly constructed where driven into the river bed and the other than the stone. The upper part of the question is approximately 500 feet long tervening space had not been filled.	ough to berth there is room  50X1-HUM  pment or warehouses arf; it is built e sloping river uay, which is , but it consists in; however, the
2.	four vessels for loadin for two other vessels a There is plenty of wate on the quay. The quay between piles, which we bank, and it is faced w used as the waiting ber only of piles. The int	m36, <b>E</b> 40-33). The quay is long end g purposes, while at the upper end waiting a loading berth.  There is no cargo handling equipitself is a properly constructed where driven into the river bed and the with stone. The upper part of the parts, is approximately 500 feet long tervening space had not been filled as in the case of the lower berths.	ough to berth there is room  50X1-HUM  pment or warehouses arf; it is built e sloping river busy, which is , but it consists in; however, the  50X1-HUM
	four vessels for loadin for two other vessels a There is plenty of wate on the quay. The quay between piles, which we bank, and it is faced wused as the waiting ber only of piles. The intriver bank was revetted	m36, <b>E</b> 40-33). The quay is long end g purposes, while at the upper end waiting a loading berth.  There is no cargo handling equipitself is a properly constructed where the driven into the river bed and the orths, is approximately 500 feet long tervening space had not been filled as in the case of the lower berths  Sawmill No. 9-10	ough to berth there is room  50X1-HUM  pment or warehouses arf; it is built e sloping river uay, which is , but it consists in; however, the  50X1-HUM is located on 50X1-HUM
2.	four vessels for loadin for two other vessels a There is plenty of water on the quay. The quay between piles, which we bank, and it is faced we used as the waiting beronly of piles. The intriver bank was revetted Keg Island (N 64-32, E long, can accommodate to	The quay is long end g purposes, while at the upper end waiting a loading berth.  There is no cargo handling equipitself is a properly constructed where driven into the river bed and the with stone. The upper part of the quarths, is approximately 500 feet long tervening space had not been filled as in the case of the lower berths  Sawmill No. 9-10  40-28). The quay, which is approximately good serves approximately good serves approximately serves approximately serves as a serve of the lower berths.	ough to berth there is room  50X1-HUM  pment or warehouses arf; it is built e sloping river uay, which is , but it consists in; however, the  50X1-HUM is located on mately 500 feet oney but there
2.	four vessels for loadin for two other vessels a There is plenty of water on the quay. The quay between piles, which we bank, and it is faced we used as the waiting beronly of piles. The intriver bank was revetted Keg Island (N 64-32. R	The quay is long end g purposes, while at the upper end waiting a loading berth.  There is no cargo handling equipitself is a properly constructed where driven into the river bed and the with stone. The upper part of the quarths, is approximately 500 feet long tervening space had not been filled as in the case of the lower berths  Sawmill No. 9-10  40-28). The quay, which is approximately good serves approximately good serves approximately serves approximately serves as a serve of the lower berths.	ough to berth there is room  50X1-HUM  pment or warehouses arf; it is built e sloping river uay, which is , but it consists in; however, the  50X1-HUM is located on mately 500 feet
2.	four vessels for loadin for two other vessels a There is plenty of water on the quay. The quay between piles, which we bank, and it is faced we used as the waiting beronly of piles. The intriver bank was revetted Keg Island (N 64-32, E long, can accommodate to	There is no cargo handling equipitself is a properly constructed where driven into the river bed and the other is approximately 500 feet long tervening space had not been filled as in the case of the lower berths.  Sawmill No. 9-10  40-28). The quay, which is approximately 500 feet long that is a reasonably good quipment on it.	ough to berth there is room  50X1-HUM  pment or warehouses arf; it is built e sloping river uay, which is , but it consists in; however, the  50X1-HUM  50X1-HUM  50X1-HUM  50X1-HUM
2.	four vessels for loadin for two other vessels a There is plenty of water on the quay. The quay between piles, which we bank, and it is faced wused as the waiting beronly of piles. The intriver bank was revetted Keg Island (N 64-32, E long, can accommodate t is no cargo handling equals to the second of the sec	-36, <b>E</b> 40-33). The quay is long end g purposes, while at the upper end waiting a loading berth.  There is no cargo handling equipitself is a properly constructed where driven into the river bed and the rith stone. The upper part of the quay is approximately 500 feet long tervening space had not been filled as in the case of the lower berths  Sawmill No. 9-10  40-28). The quay, which is approximately 500 feet long that is a reasonably good quipment on it.	ough to berth there is room  50X1-HUM  pment or warehouses arf; it is built e sloping river uay, which is , but it consists in; however, the  50X1-HUM  50X1-HUM  50X1-HUM  50X1-HUM
2.	four vessels for loadin for two other vessels a There is plenty of water on the quay. The quay between piles, which we bank, and it is faced wused as the waiting beronly of piles. The intriver bank was revetted Keg Island (N 64-32, E long, can accommodate to is no cargo handling equations.	There is no cargo handling equipitself is a properly constructed where driven into the river bed and the other is approximately 500 feet long tervening space had not been filled as in the case of the lower berths.  Sawmill No. 9-10  40-28). The quay, which is approximately 500 feet long that is a reasonably good quipment on it.	ough to berth there is room  50X1-HUM  pment or warehouses arf; it is built e sloping river uay, which is , but it consists in; however, the  50X1-HUM  50X1-HUM  50X1-HUM  50X1-HUM
2.	four vessels for loadin for two other vessels a There is plenty of water on the quay. The quay between piles, which we bank, and it is faced wused as the waiting beronly of piles. The intriver bank was revetted Keg Island (N 64-32, E long, can accommodate to is no cargo handling equations.	-36, <b>E</b> 40-33). The quay is long energy purposes, while at the upper end waiting a loading berth.  There is no cargo handling equipitself is a properly constructed where driven into the river bed and the other than the second of the quay is approximately 500 feet long tervening space had not been filled as in the case of the lower berths.  Sawmill No. 9-10  40-28). The quay, which is approximately sood quipment on it.  Sawmill No. 3  and of the Dvina River, upstream from the second of the second of the quay is approximately and and second of the quay is approximately and second of the quay is appro	pment or warehouses arf; it is built e sloping river to s
2.	four vessels for loadin for two other vessels a There is plenty of water on the quay. The quay between piles, which we bank, and it is faced we used as the waiting beronly of piles. The intriver bank was revetted Keg Island (N 64-32, R long, can accommodate the is no cargo handling equations of the east backhangelsk (N 64-34, R there is plenty of water the state of the same accommodate that is no cargo handling equations of the east backhangelsk (N 64-34, R there is plenty of water the same accommodate that is plenty of water the same accommodate that is no cargo handling equations of the east backhangelsk (N 64-34, R there is plenty of water the same accommodate that is plenty that is plenty of water the same accommodate that is plenty of water the same accommodate that is plenty of water the same accommodate that is plenty that is p	major 18 40-33). The quay is long end g purposes, while at the upper end waiting a loading berth.  There is no cargo handling equipitself is a properly constructed where driven into the river bed and the other than the stone. The upper part of the quay is approximately 500 feet long tervening space had not been filled as in the case of the lower berths.  Sawmill No. 9-10  40-28). The quay, which is approximately seed and the case of the lower berths.  Sawmill No. 9-10  Sawmill No. 9-10  Sawmill No. 3  The quay is approximately such as a proximately seed and the case of the lower berths.  The quay is approximately saw in the case of the lower berths.	pment or warehouses arf; it is built e sloping river to solve the sloping slope to solve the sloping to solve the slope the slope to solve the slope the slope to solve the slope the slo
2.	four vessels for loading for two other vessels as There is plenty of water on the quay. The quay between piles, which we bank, and it is faced we used as the waiting beronly of piles. The intriver bank was revetted.  Keg Island (N 64-32, R long, can accommodate to is no cargo handling equations of the east based on t	There is no cargo handling equipitself is a properly constructed where driven into the river bed and the other is approximately 500 feet long tervening space had not been filled as in the case of the lower berths.  Sawmill No. 9-10  40-28). The quay, which is approximately 500 feet long that is a reasonably good approach to the distance of the lower berths.  Sawmill No. 9-10  40-28). The quay, which is approximately should be a reasonably good approach to the lower berths.  Sawmill No. 3  The quay is approximately stance of the lower berths approximately should be a reasonably good approximately approximately are alongside the quay.  A considerable quantity of livers and the considerable quantity of livers.	pment or warehouses arf; it is built e sloping river tay, which is but it consists in; however, the slocated on mately 500 feet quay, but there  is located on mately 500 feet quay but there  50X1-HUM  50X1-HUM  50X1-HUM  50X1-HUM  50X1-HUM  50X1-HUM
2.	four vessels for loading for two other vessels as There is plenty of water on the quay. The quay between piles, which we bank, and it is faced we used as the waiting beronly of piles. The intriver bank was revetted.  Keg Island (N 64-32, E long, can accommodate to is no cargo handling equal to the east backhangelsk (N 64-34, E there is plenty of water as wooden parts for box itself is a half-hour jumply of coal at the supply of coal at the service of the supply of coal at the service of the servi	and a second by some	ough to berth there is room  50X1-HUM  pment or warehouses arf; it is built e sloping river uay, which is , but it consists in; however, the  50X1-HUM
2. 3.	four vessels for loading for two other vessels as the real splenty of water on the quay. The quay between piles, which we bank, and it is faced we used as the waiting beronly of piles. The intriver bank was revetted to the following can accommodate the splenty of water as wooden parts for box itself is a half-hour jumple of coal at the low. An icebreaker	and a second but the province of the quay is long end go purposes, while at the upper end waiting a loading berth.  There is no cargo handling equipitself is a properly constructed where driven into the river bed and the other than the properly constructed where driven into the river bed and the other is approximately 500 feet long than is approximately 500 feet long tervening space had not been filled as in the case of the lower berths  Sawmill No. 9-10  40-28). The quay, which is approximately show ships. It is a reasonably good quipment on it.  Sawmill No. 3  A considerable quantity of luncted and cases, were stored in the argument of the argument of the argument of the argument of the depot at Arkhangelsk Pier Station was observed bunkering at the depot	ough to berth there is room  50X1-HUM  pment or warehouses arf; it is built e sloping river uay, which is , but it consists in; however, the  50X1-HUM
2. 3.	four vessels for loading for two other vessels as There is plenty of water on the quay. The quay between piles, which we bank, and it is faced we used as the waiting beronly of piles. The intriver bank was revetted to the first bank was revetted was a second to the east bank bank bank (N 64-32, second bank). The supply of coal at the low. An icebreaker were observed replenish	sawmill No. 9-10  Was of the Dvina River, upstream from the depot at Arkhangelsk Pier Station was observed bunkering at the depot at Arkhangelsk Pier Station was observed bunkering at the depot at the supply. A vessel of about 1 is approximately 500 feet long derivening space had not been filled as in the case of the lower berths Sawmill No. 9-10  Sawmill No. 9-10  Sawmill No. 9-10  Sawmill No. 3  A considerable quantity or lung and cases, were stored in the argument of the depot at Arkhangelsk Pier Station was observed bunkering at the depot at the supply. A vessel of about 1	ough to berth there is room  50X1-HUM  pment or warehouses arf; it is built e sloping river that is built to sloping river that is but it consists in; however, the  50X1-HUM
2. 3.	four vessels for loading for two other vessels as There is plenty of water on the quay. The quay between piles, which we bank, and it is faced we used as the waiting beronly of piles. The intriver bank was revetted.  Keg Island (N 64-32, R long, can accommodate to is no cargo handling equations of the same as wooden parts for box itself is a half-hour justelf is a	The quay is long endergour purposes, while at the upper endowaiting a loading berth.  There is no cargo handling equipitself is a properly constructed where driven into the river bed and the other than the state of the quay is approximately 500 feet long the remaining space had not been filled as in the case of the lower berths.  Sawmill No. 9-10  40-28). The quay, which is approximately swo ships. It is a reasonably good quipment on it.  Sawmill No. 3  The quay is approximately are alongside the quay  A considerable quantity of lucters and cases, were stored in the are coursely by car from the center of Are the depot at Arkhangelsk Pier Station was observed bunkering at the depot ing the supply. A vessel of about a scharging a cargo of coal at the depot estween the quay at Sawmill No. 16-11	ough to berth there is room  50X1-HUM  pment or warehouses arf; it is built e sloping river that it consists in; however, the  50X1-HUM
2. 3.	four vessels for loading for two other vessels as There is plenty of water on the quay. The quay between piles, which we bank, and it is faced we used as the waiting beronly of piles. The intriver bank was revetted.  Keg Island (N 64-32, R long, can accommodate to is no cargo handling equations of the supply of water is plenty of water as wooden parts for box itself is a half-hour just the low. An icebreaker were observed replenish tons dead weight was disolombala, which lies be shipyard. This coal desired.	The quay is long endergour purposes, while at the upper endowaiting a loading berth.  There is no cargo handling equipitself is a properly constructed where driven into the river bed and the other than the same of the quay is approximately 500 feet long servening space had not been filled as in the case of the lower berths.  Sawmill No. 9-10  40-28). The quay, which is approximately swo ships. It is a reasonably good suipment on it.  Sawmill No. 3  The quay is approximately are alongside the quay  A considerable quantity of luctures and cases, were stored in the are sourced bunkering at the depott at Arkhangelsk Pier Station was observed bunkering at the depott is capating a cargo of coal at the depott is equipped with four cranes, see the sequipped with four cranes.	ough to berth there is room  50X1-HUM  pment or warehouses arf; it is built e sloping river that it consists in; however, the  50X1-HUM  70X1-HUM
2. 3.	four vessels for loading for two other vessels as There is plenty of water on the quay. The quay between piles, which we bank, and it is faced we used as the waiting beronly of piles. The intriver bank was revetted to the first bank was revetted was accommodate to the care of the first bank was revetted is no cargo handling equations. The supply of water as wooden parts for box itself is a half-hour just below. An icebreaker were observed replenish tons dead weight was discolombala, which lies be shipyard. This coal de has a capacity of five	Sawmill No. 3  Sawmill No. 3  The quay is long end waiting a loading berth.  There is no cargo handling equipitself is a properly constructed where driven into the river bed and the other states. The upper part of the quay is approximately 500 feet long servening space had not been filled as in the case of the lower berths.  Sawmill No. 9-10  40-28). The quay, which is approximately swo ships. It is a reasonably good quipment on it.  Sawmill No. 3  The quay is approximately and it is a proximately servening space had not been filled as in the case of the lower berths.  Sawmill No. 9-10  40-28). The quay which is approximately servening at the depot at Arkhangelsk Pier Station was observed bunkering at the depot at Arkhangelsk Pier Station was observed bunkering at the depot ing the supply. A vessel of about a scharging a cargo of coal at the depot is equipped with four cranes, extens.	ough to berth there is room  50X1-HUM  pment or warehouses arf; it is built e sloping river that it consists in; however, the  50X1-HUM
2. 3. 4.	four vessels for loading for two other vessels as There is plenty of water on the quay. The quay between piles, which we bank, and it is faced we used as the waiting beronly of piles. The intriver bank was revetted to the first bank was revetted was accommodate to the care of the first bank was revetted is no cargo handling equations. The supply of water as wooden parts for box itself is a half-hour just below. An icebreaker were observed replenish tons dead weight was discolombala, which lies be shipyard. This coal de has a capacity of five	The quay is long endergour purposes, while at the upper endowaiting a loading berth.  There is no cargo handling equipitself is a properly constructed where driven into the river bed and the other than the same of the quay is approximately 500 feet long servening space had not been filled as in the case of the lower berths.  Sawmill No. 9-10  40-28). The quay, which is approximately swo ships. It is a reasonably good suipment on it.  Sawmill No. 3  The quay is approximately are alongside the quay  A considerable quantity of luctures and cases, were stored in the are sourced bunkering at the depott at Arkhangelsk Pier Station was observed bunkering at the depott is capating a cargo of coal at the depott is equipped with four cranes, see the sequipped with four cranes.	ough to berth there is room  50X1-HUM  pment or warehouses arf; it is built e sloping river that it consists in; however, the  50X1-HUM

50X1-HUM

a wooden tower under construction on the west side of Kharlov Island (N 68-49, E 37-21).

9.

Sanitized Copy Approved for Release 2010/11/09 : CIA-RDP80-00810A002300530009-9

SECRET/CONTROL US OFFICIALS ONLY